ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0114, W0155, W0151, W0149, W0139, W0118, W0141, W	NA, Vinayaka Lyt 4th Crs	Doddamma Temple
Segment No.	**Total Length (m)**	
7/C-W0114/S050321	794.56	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	93.26	77.598873	13.072739	77.598702	13.071913	Jakkur double road	Ayyappa temple road
2	103.22	77.599216	13.072756	77.599004	13.071847	Jakkur double road	Ayyappa temple road
3	114.78	77.599541	13.072787	77.599302	13.071776	Jakkur double road	Ayyappa temple road
4	126.85	77.599879	13.072831	77.599631	13.071710	Jakkur double road	Ayyappa temple road
5	56.28	77.600037	13.072150	77.599924	13.071653	Ayyappa temple road	Dead End
6	145.15	77.600524	13.072870	77.600244	13.071587	Jakkur double road	Ayyappa temple road
7	155.02	77.600876	13.072879	77.600560	13.071513	Jakkur double road	Ayyappa temple road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to drains of 4th to 6th Cross Roads of Jakkur Layout in ward no 07, Byatarayanapura, Kodigehalli Sub Division	5000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	1.Construction of RCC Drain.2.Providing and laying Rcc Covering slabs.	007-18-000003
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/81/17-18	02/03/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**

9/06/2018	18/06/2020	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Executive Engineer, K.R.I.D.L		0.00
Phone No.	**E-Mail ID**	
9480826123		

Field Inspection Details

Number of Trees	Any Other Information	Name
3		Pushpalatha.N D
Date of Inspection	**Remarks**	
05/07/2018		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0114, W0155, W0151, W0149,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	R.L.Parameshwaraiah	11/07/2018	20/07/2018	As proposed
SE	Vasu K M	07/07/2018	20/07/2018	Completed
EE	Mohandas H.T	06/07/2018	20/07/2018	verified
AEE	Ranganath	06/07/2018	20/07/2018	verified
AE	Pushpalatha.N.D	06/07/2018	20/07/2018	Mobile Verification Done
AE	Pushpalatha.N.D	20/06/2018	20/07/2018	Forwarded

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0114, W0155, W0151, W0149, W

Pushpa. N.D
AE(Ver)

Assistant Executive Engineer,
Kodigehalli Sub Division,
Yelahanka Zone, B.B.M.P.,
Bangalore.